Historical Floods: Delaware River at Washington Crossing, New Jersey

Latitude: 40.294 Period of Record: 1903-Present Longitude: -74.869 Flood Stage: 16 ft

Last Flood: 9/8/2011 Number of Floods: 10

Date of Flood	Crest (ft)	Streamflow (cfs)	Category	Code
10/11/1903	25.50	-9,999	Major	C1
3/13/1936	20.21	-9,999	Minor	C1
3/19/1936	21.30	-9,999	Minor	C1
8/20/1955	27.77	-9,999	Major	C1
9/19/2004	22.00	-9,999	Moderate	C1
9/28/2004	20.20	-9,999	Minor	C1
4/4/2005	23.10	-9,999	Moderate	C1
6/29/2006	22.54	-9,999	Moderate	C1
8/29/2011	16.06	-9,999	Minor	none
9/8/2011	20.40	-9,999	Moderate	none

Drainage Area: 6735 sq mi Gage Datum: 26.14 ft MSL

Main Stem Delaware Basin

County of Gage: Mercer County of Forecast Point: Bucks

Historical Floods: Delaware River at Washington Crossing, New Jersey

Latitude: 40.294 Period of Record: 1903-Present Longitude: -74.869

Flood Stage: 16 ft Last Flood: 9/8/2011 Number of Floods: 10

Date of Flood Crest (ft) Streamflow (cfs) Category Code

-9999 signifies missing data

Description

MARFC Codes

Code

C1	Crest information looks unreliable and incomplete and not used in frequency calculations. Some of the floods are based on current flood stage and
	nearby gage information.

- C2 Crest information looks reliable despite potential problems. This data was used in frequency calculations.
- C3 Crest height estimated by the USGS.
- C4 Crest height is from the National Weather Service.
- C5 Crest height affected by backwater.
- Cf Crest occurred at a previous flood stage that is lower than the current flood stage. The crests below the new flood stage are not used in flood frequency calculations.
- Crest from USGS yearly peak and/or date is different than the crest we provide. In many cases MARFC uses crest based on backwater or ice effects.

 Crest month or day of occurrence has been estimated by The Middle Atlantic River Forecast Center usually based on nearby gage information.
- C8 Crest date (day) in the month is unknown.
- C9 Flow is an estimate.
- F1 Flow affected by regulation or diversion and in some cases to an unknown degree.
- F2 Flow effected by snow-melt, ice jam or debris jam break up.
- F3 Flow affected by dam failure.
- Flow All or part of the record affected by urbanization, mining, agricultural changes, channelization or other factors.
- F5 Gage height at a different site and/or datum.
- G1 Gage is not an official USGS gage with crests provided by the NWS. Crest information looks unreliable and incomplete and not used in flood frequency
- G2 calculations.

Cago datum changed during this year

Drainage Area: 6735 sq mi Gage Datum: 26.14 ft MSL County of Gage: Mercer
Main Stem Delaware Basin
County of Forecast Point: Bucks

Created: 3/19/2016 8:24:07 AM Page 2 of 2